

Methodology	AS 4133.4.1
Client	AECOM
Address	Level 21/420 George St, Sydney NSW 2000
Project	Chowder Bay DFI (60740478)
MG Project No.	S26240-1
Report No.	S116569-AS_PLT
Sampling Method	Sampled by Client - results apply to the sample as received
Preparation Method	Prepared in accordance with the test method

MG Sample No.	Sample ID	Date Sampled	Date Tested	Lithology	Moisture Condition	Test Type	Failure Load (kN)	Uncorrected Point Load Strength (Is)	Corrected Point Load Strength Index Is(50)	Failure Mode
S116569	ABH01 0.3-0.4m	Unknown	27/05/2026	Rock Core	Moist	Diametral	3.1	1.3	1.3	1
						Axial	3.0	1.3	1.3	1
S116570	ABH01 1.28-1.39m	Unknown	27/05/2026	Rock Core	Moist	Diametral	7.1	3.1	3.0	1
						Axial	4.3	2.0	1.9	1
S116571	ABH01 2.2-2.31m	Unknown	27/05/2026	Rock Core	Moist	Diametral	1.1	0.46	0.46	1
						Axial	2.2	1.0	0.99	1
S116572	ABH01 3.13-3.23m	Unknown	27/05/2026	Rock Core	Moist	Diametral	4.3	1.8	1.8	1
						Axial	0.75	0.36	0.34	1
S116573	ABH01 4.63-4.73m	Unknown	27/05/2026	Rock Core	Moist	Diametral	1.4	0.62	0.60	1
						Axial	1.5	0.51	0.53	1
S116574	ABH01 5.79-5.87m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.36	0.16	0.16	3
						Axial	0.71	0.27	0.28	1
S116575	ABH01 6.75-6.84m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.6	0.67	0.66	1
						Axial	1.7	0.88	0.83	1
S116576	ABH01 7.79-7.88m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.8	0.78	0.77	1
						Axial	2.6	1.1	1.1	1
S116577	ABH01 8.18-8.27m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.34	0.15	0.14	1
						Axial	0.22	0.10	0.10	1
S116578	ABH01 9.2-9.29m	Unknown	27/05/2026	Sandstone	Moist	Diametral	2.2	0.95	0.94	1
						Axial	2.1	1.2	1.1	1

Failure Mode Key 1 - Fracture through fabric of specimen oblique to bedding, not influenced by weak planes. 2 - Fracture along bedding. 3 - Fracture influenced by pre-existing plane, microfracture, vein or chemical alteration. 4 - Chip or partial fracture.	Storage History of Test Specimens Core Box
---	--

Notes

  Accredited for compliance with ISO/IEC 17025 - Testing. NATA Accredited Laboratory Number: 14874 Macquarie Geotechnical Pty Ltd 14 Carter Street, Lidcombe NSW 2141 (Sydney Laboratory)	Authorised Signatory  Jacob Lloyd
	Date of Issue 02/06/2026

Methodology	AS 4133.4.1
Client	AECOM
Address	Level 21/420 George St, Sydney NSW 2000
Project	Chowder Bay DFI (60740478)
MG Project No.	S26240-1
Report No.	S116579-AS_PLT
Sampling Method	Sampled by Client - results apply to the sample as received
Preparation Method	Prepared in accordance with the test method

MG Sample No.	Sample ID	Date Sampled	Date Tested	Lithology	Moisture Condition	Test Type	Failure Load (kN)	Uncorrected Point Load Strength (Is)	Corrected Point Load Strength Index Is(50)	Failure Mode
S116579	ABH01 10.57-10.66m	Unknown	27/05/2026	Sandstone	Moist	Diametral	2.9	1.3	1.3	1
						Axial	2.6	1.2	1.2	1
S116580	ABH01 11.57-11.65m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.1	0.48	0.47	1
						Axial	1.8	0.89	0.85	1
S116581	ABH01 12.41-12.5m	Unknown	27/05/2026	Sandstone	Moist	Diametral	2.8	1.3	1.3	1
						Axial	1.4	0.71	0.67	1
S116582	ABH02 4.72-4.77m	Unknown	27/05/2026	Sandstone	Moist	-	-	-	-	-
						Axial	0.58	0.27	0.26	1
S116583	ABH02 5.89-5.76m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.88	0.40	0.39	1
						Axial	1.1	0.52	0.50	1
S116584	ABH02 6.72-6.82m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.6	0.71	0.69	1
						Axial	1.6	0.70	0.69	1
S116585	ABH02 7.54-7.65m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.95	0.41	0.40	1
						Axial	1.4	0.60	0.59	1
S116586	ABH02 8.28-8.37m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.4	0.60	0.59	1
						Axial	1.6	0.80	0.77	1
S116587	ABH03 5.47-5.56m	Unknown	27/05/2026	Sandstone	Moist	Diametral	2.1	0.93	0.91	1
						Axial	2.0	0.87	0.86	1
S116588	ABH03 6.56-6.66m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.67	0.29	0.29	1
						Axial	0.98	0.48	0.46	1

Failure Mode Key

- 1 - Fracture through fabric of specimen oblique to bedding, not influenced by weak planes.
- 2 - Fracture along bedding.
- 3 - Fracture influenced by pre-existing plane, microfracture, vein or chemical alteration.
- 4 - Chip or partial fracture.

Storage History of Test Specimens

Core Box

Notes



Accredited for compliance with ISO/IEC 17025 - Testing.

NATA Accredited Laboratory Number: 14874

Macquarie Geotechnical Pty Ltd

14 Carter Street, Lidcombe NSW 2141 (Sydney Laboratory)

Authorised Signatory



Jacob Lloyd

Date of Issue

02/06/2026

Results relate only to the samples tested.
This document shall not be reproduced, except in full.

Methodology	AS 4133.4.1
Client	AECOM
Address	Level 21/420 George St, Sydney NSW 2000
Project	Chowder Bay DFI (60740478)
MG Project No.	S26240-1
Report No.	S116589-AS_PLT
Sampling Method	Sampled by Client - results apply to the sample as received
Preparation Method	Prepared in accordance with the test method

MG Sample No.	Sample ID	Date Sampled	Date Tested	Lithology	Moisture Condition	Test Type	Failure Load (kN)	Uncorrected Point Load Strength (Is)	Corrected Point Load Strength Index Is(50)	Failure Mode
S116589	ABH03 7.42-7.54m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.9	0.86	0.84	1
						Axial	2.1	0.94	0.91	1
S116590	ABH03 9.67-9.77m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.4	0.65	0.63	1
						Axial	1.5	0.71	0.69	1
S116591	ABH03 10.08-10.15m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.92	0.42	0.41	1
						Axial	1.1	0.45	0.45	1
S116592	ABH03 12.76-12.85m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.62	0.27	0.27	1
						Axial	0.74	0.37	0.35	1
S116593	ABH03 13.58-13.67m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.62	0.28	0.27	3
						Axial	2.1	0.82	0.82	1
S116594	ABH03 14.37-14.35m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.3	0.61	0.59	1
						Axial	1.4	0.63	0.61	1
S116595	ABH03 16.66-16.74m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.9	0.90	0.86	1
						Axial	1.5	0.78	0.73	1
S116596	ABH03 17.9-17.96m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.6	0.73	0.71	1
						Axial	1.5	0.98	0.87	1
S116597	ABH03 18.66-18.76m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.5	0.68	0.66	1
						Axial	1.9	0.94	0.89	1
S116598	ABH03 19.69-19.77m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.7	0.79	0.77	1
						Axial	1.6	0.77	0.74	1

Failure Mode Key 1 - Fracture through fabric of specimen oblique to bedding, not influenced by weak planes. 2 - Fracture along bedding. 3 - Fracture influenced by pre-existing plane, microfracture, vein or chemical alteration. 4 - Chip or partial fracture.	Storage History of Test Specimens Core Box
---	--

Notes

  Accredited for compliance with ISO/IEC 17025 - Testing. NATA Accredited Laboratory Number: 14874 Macquarie Geotechnical Pty Ltd 14 Carter Street, Lidcombe NSW 2141 (Sydney Laboratory)	Authorised Signatory  Jacob Lloyd
	Date of Issue 02/06/2026

Methodology	AS 4133.4.1
Client	AECOM
Address	Level 21/420 George St, Sydney NSW 2000
Project	Chowder Bay DFI (60740478)
MG Project No.	S26240-1
Report No.	S116599-AS_PLT
Sampling Method	Sampled by Client - results apply to the sample as received
Preparation Method	Prepared in accordance with the test method

MG Sample No.	Sample ID	Date Sampled	Date Tested	Lithology	Moisture Condition	Test Type	Failure Load (kN)	Uncorrected Point Load Strength (Is)	Corrected Point Load Strength Index Is(50)	Failure Mode
S116599	ABH03 20.35-20.45m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.3	0.60	0.59	1
						Axial	1.6	0.70	0.69	1
S116600	ABH04 7.6-7.68m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.7	0.81	0.78	1
						Axial	1.8	1.1	0.98	1
S116601	ABH04 8.25-8.29m	Unknown	27/05/2026	Sandstone	Moist	-	-	-	-	-
						Axial	0.46	0.21	0.20	1
S116602	ABH04 11.78-11.84m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.86	0.40	0.39	1
						Axial	1.1	0.47	0.47	1
S116603	ABH04 12.42-12.5m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.40	0.18	0.17	1
						Axial	0.38	0.19	0.18	1
S116604	ABH04 13.17-13.21m	Unknown	27/05/2026	Sandstone	Moist	-	-	-	-	-
						Axial	0.88	0.41	0.40	1
S116605	ABH04 15.69-15.76m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.24	0.12	0.11	1
						Axial	0.26	0.13	0.13	1
S116606	ABH04 16.62-16.71m	Unknown	27/05/2026	Sandstone	Moist	Diametral	0.82	0.37	0.36	1
						Axial	0.86	0.41	0.39	1
S116607	ABH04 17.34-17.44m	Unknown	27/05/2026	Sandstone	Moist	Diametral	2.5	1.1	1.1	1
						Axial	4.0	2.0	1.9	1
S116608	ABH04 18.32-18.4m	Unknown	27/05/2026	Sandstone	Moist	Diametral	1.7	0.79	0.76	1
						Axial	2.8	1.2	1.2	1

Failure Mode Key	Storage History of Test Specimens
1 - Fracture through fabric of specimen oblique to bedding, not influenced by weak planes. 2 - Fracture along bedding. 3 - Fracture influenced by pre-existing plane, microfracture, vein or chemical alteration. 4 - Chip or partial fracture.	Core Box

Notes

 	Accredited for compliance with ISO/IEC 17025 - Testing. NATA Accredited Laboratory Number: 14874 Macquarie Geotechnical Pty Ltd 14 Carter Street, Lidcombe NSW 2141 (Sydney Laboratory)	Authorised Signatory  Jacob Lloyd
		Date of Issue 02/06/2026

Methodology	AS 4133.4.1
Client	AECOM
Address	Level 21/420 George St, Sydney NSW 2000
Project	Chowder Bay DFI (60740478)
MG Project No.	S26240-1
Report No.	S116609-AS_PLT

Sampling Method	Sampled by Client - results apply to the sample as received
Preparation Method	Prepared in accordance with the test method

MG Sample No.	Sample ID	Date Sampled	Date Tested	Lithology	Moisture Condition	Test Type	Failure Load (kN)	Uncorrected Point Load Strength (Is)	Corrected Point Load Strength Index Is(50)	Failure Mode
S116609	ABH05 5.8-5.89m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.030	0.022	0.019	1
						Axial	0.020	0.012	0.011	1
S116610	ABH05 6.46-6.56m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.3	0.62	0.59	1
						Axial	2.5	1.2	1.1	1
S116611	ABH05 7.46-7.57m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.90	0.44	0.42	1
						Axial	0.77	0.37	0.35	1
S116612	ABH05 8.28-8.36m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.1	0.51	0.49	1
						Axial	1.6	0.80	0.76	1
S116613	ABH05 1.64-1.73m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.22	0.095	0.094	1
						Axial	0.28	0.11	0.11	1
S116614	ABH05 2.35-2.44m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.18	0.075	0.074	1
						Axial	0.41	0.18	0.18	1
S116615	ABH05 3.24-3.32m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.48	0.21	0.21	1
						Axial	0.44	0.20	0.19	1
S116616	ABH05 4.45-4.55m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.31	0.13	0.13	1
						Axial	0.25	0.11	0.11	1
S116617	ABH05 5.5-5.58m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.22	0.093	0.092	1
						Axial	0.18	0.087	0.083	1
S116618	ABH07 1.42-1.51m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.25	0.11	0.11	1
						Axial	0.49	0.23	0.22	1

Failure Mode Key 1 - Fracture through fabric of specimen oblique to bedding, not influenced by weak planes. 2 - Fracture along bedding. 3 - Fracture influenced by pre-existing plane, microfracture, vein or chemical alteration. 4 - Chip or partial fracture.	Storage History of Test Specimens Core Box
--	--

Notes

  Accredited for compliance with ISO/IEC 17025 - Testing. NATA Accredited Laboratory Number: 14874 Macquarie Geotechnical Pty Ltd 14 Carter Street, Lidcombe NSW 2141 (Sydney Laboratory)	Authorised Signatory  Date of Issue 02/06/2026

Methodology	AS 4133.4.1
Client	AECOM
Address	Level 21/420 George St, Sydney NSW 2000
Project	Chowder Bay DFI (60740478)
MG Project No.	S26240-1
Report No.	S116619-AS_PLT

Sampling Method	Sampled by Client - results apply to the sample as received
Preparation Method	Prepared in accordance with the test method

MG Sample No.	Sample ID	Date Sampled	Date Tested	Lithology	Moisture Condition	Test Type	Failure Load (kN)	Uncorrected Point Load Strength (Is)	Corrected Point Load Strength Index Is(50)	Failure Mode
S116619	ABH07 2.52-5.63m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.5	0.69	0.67	1
						Axial	1.3	0.53	0.53	1
S116620	ABH07 3.46-3.56m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.34	0.15	0.14	1
						Axial	0.62	0.29	0.28	1
S116621	ABH07 4.34-4.42m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.2	0.53	0.52	1
						Axial	1.9	0.86	0.84	1
S116622	ABH07 5.39-5.47m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.1	0.47	0.46	1
						Axial	1.6	0.80	0.76	1
S116623	ABH08 1.43-1.53m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.3	0.60	0.58	1
						Axial	2.2	0.85	0.86	1
S116624	ABH08 2.4-2.5m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.7	0.76	0.74	1
						Axial	1.5	0.67	0.66	1
S116625	ABH08 3.7-3.8m	Unknown	28/05/2026	Sandstone	Moist	Diametral	1.5	0.66	0.64	1
						Axial	1.2	0.51	0.50	1
S116626	ABH08 4.57-4.65m	Unknown	28/05/2026	Sandstone	Moist	Diametral	2.1	0.96	0.93	1
						Axial	1.6	0.75	0.73	1
S116627	ABH08 5-5.1m	Unknown	28/05/2026	Sandstone	Moist	Diametral	0.74	0.33	0.33	1
						Axial	0.46	0.27	0.25	1

Failure Mode Key 1 - Fracture through fabric of specimen oblique to bedding, not influenced by weak planes. 2 - Fracture along bedding. 3 - Fracture influenced by pre-existing plane, microfracture, vein or chemical alteration. 4 - Chip or partial fracture.	Storage History of Test Specimens Core Box
--	--

Notes

  Accredited for compliance with ISO/IEC 17025 - Testing. NATA Accredited Laboratory Number: 14874 Macquarie Geotechnical Pty Ltd 14 Carter Street, Lidcombe NSW 2141 (Sydney Laboratory)	Authorised Signatory  Date of Issue 02/06/2026