

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush east of M1

Project No: 60739890

Logged by: KM

Start Date: 12/11/25

Checked by: PW

End Date: 12/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 303305.00

RL: 325 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6194523.20

Ver. Datum: AHD

Total Depth: 0.6 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	2	D: 0.00-0.26 m ES: 0.00-0.26 m PID=0.2 PPM D: 0.26-0.60 m ES: 0.26-0.60 m PID=0.1 PPM	Not Encountered	325.0	0.0			TOPSOIL - Silty SAND: medium grained, dark brown; trace rootlets.	D		TOPSOIL
		4										
		3				CH	CLAY: high plasticity, pale yellow brown to pale brown; trace sand.	w < PL	VSt to H	RESIDUAL		
		5										
		15										
		17/50										Terminated at 0.60 m. Refusal on inferred top of rock.

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush east of M1

Project No: 60739890



Logged by: KM
Start Date: 12/11/25

Checked by: PW
End Date: 12/11/25
Location Meth.: DGPS

Driller: AECOM	Hole Diameter: 76 mm
Drill Rig: Hand Auger	Inclination: 90°
Total Depth: 1.32 m	Bearing: N/A

Easting: 303326.00
Northing: 6194935.70
Hor. Datum: MGA2020-56

RL: 315 m
Ver. Datum: AHD
Surface: Residual Soil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	2	D: 0.00-1.32 m ES: 0.00-1.32 m PID=0.4 PPM	Not Encountered	315.0	0.0		CH	Silty CLAY: high plasticity, pale brown; trace sand; trace gravel, fine to medium grained.	w < PL	VSt to H	RESIDUAL
		6										
		7										
		8										
		6										
		11										
		9										
		7										
		7										
		10										
		16										
		14										
		23										
		314.0			1.0							
		From 1.2m, becoming pale brown, mottled red, trace XW sandstone, fine to coarse, angular										
		Terminated at 1.32 m. Refusal on inferred top of rock.										
	21		313.0	2.0								
	25											
	30/30											

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush east of M1

Project No: 60739890

Logged by: AL/KM

Start Date: 12/11/25

Checked by: PW

End Date: 12/11/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 2.2 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 303221.30



Northing: 6195124.50

Hor. Datum: MGA2020-56

RL: 315 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)		
HA	U	1	D: 0.00-0.32 m ES: 0.00-0.32 m PID=0.3 PPM	Not Encountered	315.0	0.0			TOPSOIL - Clayey SAND: fine to coarse grained, dark brown; trace gravel, fine to medium grained, sub-angular, sandstone; trace rootlets.	D		TOPSOIL		
		2												
		2												
		3	D: 0.32-0.60 m ES: 0.32-0.60 m PID=0 PPM							FILL - Sandy CLAY: medium plasticity, dark brown; sand, fine to medium grained; trace gravel, fine to coarse grained, sub-angular, sandstone.	w < PL		FILL	
		2												
		4												
		9	D: 0.60-0.95 m ES: 0.60-0.95 m PID=0 PPM							FILL - Sandy Organic CLAY: low to medium plasticity, yellow brown; sand, fine to medium grained; trace gravel, fine to coarse grained, sub-angular, sandstone.				
		5												
		7												
		11	D: 0.95-1.15 m ES: 0.95-1.15 m PID=0.1 PPM							From 0.95 m to 1.15 m, becoming yellow brown.				
		9												
		7	D: 1.15-1.61 m ES: 1.15-1.61 m PID=0.1 PPM								w < PL			
		7												
		10												
		10												
		12												
		14	D: 1.61-2.20 m ES: 1.61-2.20 m PID=0 PPM							SP	SAND: medium to coarse grained, brown mottled yellow; with gravel, fine to medium grained, sub-angular, sandstone.			RESIDUAL
		15												
		30												
													M	VD
					313.0	2.0								
									Terminated at 2.20 m. Target depth.					

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush east of M1

Project No: 60739890
Logged by: AL
Start Date: 05/11/25

Checked by: PW
End Date: 05/11/25
Location Meth.: DGPS

Driller: AECOM	Hole Diameter: 76 mm
Drill Rig: Hand Auger	Inclination: 90°
Total Depth: 0.2 m	Bearing: N/A

Easting: 303182.20
Northing: 6195302.00
Hor. Datum: MGA2020-56

RL: 310 m
Ver. Datum: AHD
Surface: Fill

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	4	D: 0.00-0.20 m ES: 0.00-0.20 m PID=0.2 PPM	Not Encountered	310.0	0.0			FILL - Gravelly SAND: fine to coarse grained, dark brown; gravel, fine to coarse grained, sub-angular to angular, sandstone.	D		FILL
		11										
		23			309.0	1.0			Terminated at 0.20 m. Hand auger refusal.			
		30/70										

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush east of M1

Project No: 60739890

Logged by: AL

Start Date: 12/11/25

Checked by: PW

End Date: 12/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 303186.90

RL: 309 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6195298.00

Ver. Datum: AHD

Total Depth: 2.2 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	3	D: 0.00-0.70 m	Not Encountered	309.0	0.0			TOPSOIL - Sandy CLAY: low to medium plasticity, dark brown; sand, fine to coarse grained; trace rootlets.	w < PL		TOPSOIL
		3										
		1										
		1										
		2										
		2										
		3	D: 0.70-1.60 m						From 0.59 m, becoming brown.			
		4			CI	Silty CLAY: medium plasticity, brown; trace sand, fine to coarse grained.	w ≈ PL	St to VSt	RESIDUAL			
		6										
		6										
		6										
		6										
		7										
		6										
		5										
		7										
		9										
		13										
		13										
		12										
13	D: 1.60-2.10 m						CL	Sandy CLAY: low plasticity, yellow brown mottled red; sand, fine to medium grained; trace gravel, fine to coarse grained, sub-rounded, sandstone.	w < PL	H		
30		D: 2.10-2.20 m										

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland through Firetrail No. 8e

Project No: 60739890

Logged by: AL

Start Date: 19/11/25

Checked by: PW

End Date: 19/11/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 1.33 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 302962.90

Northing: 6194638.70

Hor. Datum: MGA2020-56

RL: 320 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)					
HA	U	2	D: 0.00-0.43 m	Not Encountered	320.0	0.0			TOPSOIL - Silty CLAY: low plasticity, brown; with sand, fine to coarse grained; trace gravel, fine to coarse grained, sub-angular, sandstone; trace rootlets.	w < PL		TOPSOIL					
		2															
		4															
		5															
		5															
		6	D: 0.43-0.73 m			CI	Sandy CLAY: medium plasticity, yellow brown mottled orange; sand, fine to coarse grained.	w < PL	VSt	RESIDUAL							
		7															
		4									D: 0.73-1.33 m		SP	Gravelly SAND: medium grained, yellow brown mottled red; gravel, fine to medium grained, sub-angular, XW sandstone.	D	MD to D	EXTREMELY WEATHERED SANDSTONE
		2															
		3															
		6															
		8															
		10															
		10									Terminated at 1.33 m. Refusal on inferred top of rock.						
		7															
10																	
23																	
5/50																	

Client: TfNSW
Project: Picton Road Upgrade
Location: Grassland through Firetrail No. 8e

Project No: 60739890
Logged by: AL
Start Date: 19/11/25
Checked by: PW
End Date: 19/11/25
Location Meth.: DGPS
RL: 311 m
Ver. Datum: AHD
Surface: Topsoil

Driller: AECOM
Drill Rig: Hand Auger
Total Depth: 1.35 m
Hole Diameter: 76 mm
Inclination: 90°
Bearing: N/A

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	2	D: 0.00-0.45 m ES: 0.00-0.45 m PID=0.3 PPM	Not Encountered	311.0	0.0			TOPSOIL - Sandy CLAY: low to medium plasticity, brown; sand, fine to coarse grained; trace gravel, fine to medium grained, sub-angular, sandstone.	w < PL		TOPSOIL
		3										
		3										
		4										
		4	D: 0.45-0.73 m ES: 0.45-0.73 m PID=0.1 PPM					FILL - Sandy CLAY: medium plasticity, pale brown; sand, fine to coarse grained; trace gravel, fine to medium grained, sub-angular to sub-rounded sandstone.	w < PL		FILL	
		5										
		4										
		4										
		7	D: 0.73-1.20 m ES: 0.73-1.20 m PID=0 PPM				CI-CH	Sandy CLAY: medium to high plasticity, yellow brown mottled orange and red; sand, fine to coarse grained.	w < PL	St to H	RESIDUAL	
		11										
		16										
		16										
		18	D: 1.20-1.35 m ES: 1.20-1.35 m PID=0 PPM				SP	SAND: fine to coarse grained, orange grey; trace gravel, fine to coarse grained, angular, XW sandstone.	D	VD	EXTREMELY WEATHERED SANDSTONE	
		22										
		30					Terminated at 1.35 m. Refusal on inferred top of rock.					

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Grassland through Firetrail No. 8e

Project No: 60739890
Logged by: AL
Start Date: 05/11/25
Easting: 303046.60
Northing: 6194968.50
Hor. Datum: MGA2020-56

Checked by: PW
End Date: 05/11/25
Location Meth.: DGPS
RL: 314 m
Ver. Datum: AHD
Surface: Topsoil

Driller: AECOM	Hole Diameter: 76 mm
Drill Rig: Hand Auger	Inclination: 90°
Total Depth: 0.7 m	Bearing: N/A

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.30 m ES: 0.00-0.30 m PID=0.4 PPM	Not Encountered	314.0	0.0			TOPSOIL - Sandy CLAY: medium plasticity, dark brown; sand, fine to coarse grained; trace rootlets.	w < PL		TOPSOIL
		2										
		1					D: 0.30-0.58 m ES: 0.30-0.58 m PID=0.3 PPM		CL-CI	Sandy CLAY: low to medium plasticity, yellow brown; sand, fine to medium grained.	w < PL	F
		2										
		3										
		13	D: 0.58-0.70 m ES: 0.58-0.70 m PID=0.4 PPM					SP	SAND: fine to coarse grained, pale brown mottled red.	w > PL	VSt	
		16								D	VD	
		30										
		20/20										
					313.0	1.0						
					312.0	2.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland through Firetrail No. 8e

Project No: 60739890

Logged by: AL

Start Date: 05/11/25

Checked by: PW

End Date: 05/11/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 1.7 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 302960.10

Northing: 6195056.50

Hor. Datum: MGA2020-56

RL: 319 m

Ver. Datum: AHD

Surface: Topsoil

[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland near Cataract Creek south of Picton Road

Project No: 60739890

Logged by: AL

Start Date: 06/11/25

Checked by: PW

End Date: 06/11/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: hand auger

Total Depth: 1.7 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 302769.90

Northing: 6195358.60

Hor. Datum: MGA2020-56

RL: 297 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.60 m ES: 0.00-0.60 m PID=0 PPM	Not Encountered	297.0	0.0			TOPSOIL - Clayey SAND: fine to coarse grained, dark brown; trace rootlets.	M		TOPSOIL
		2							FILL - Clayey SAND: fine to coarse grained, dark brown; trace gravel, fine to coarse grained, sub-angular, sandstone .	M		FILL
		4										
		3										
		5										
		7										
		3	D: 0.60-1.70 m ES: 0.60-1.70 m PID=0 PPM					CI-CH	Sandy CLAY: medium to high plasticity, dark brown; sand, fine to coarse grained .	w ≈ PL St to VSt		RESIDUAL
		3										
		5										
		7										
		8			296.0	1.0						
		6										
		5										
		5										
		3										
		3										
		4										
		5							Terminated at 1.70 m. Target depth.			
		5										
		6										
					295.0	2.0						
					294.0	3.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland near Cataract Creek south of Picton Road

Project No: 60739890

Logged by: AL

Start Date: 19/11/25

Checked by: PW

End Date: 19/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 302763.90

RL: 295 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6195360.30

Ver. Datum: AHD

Total Depth: 0.16 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Residual Soil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.16 m		295.0	0.0		SM	Silty SAND: fine to coarse grained, brown; with gravel, fine to coarse grained, sub-angular to sub-rounded, XW sandstone.	W	H	RESIDUAL
		2										
		1/5										
									Terminated at 0.16 m. Refusal on inferred top of rock.			

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland near Cataract Creek south of Picton Road

Project No: 60739890

Logged by: AL

Start Date: 09/11/25

Checked by: PW

End Date: 09/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 303003.90

RL: 304 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6195340.70

Ver. Datum: AHD

Total Depth: 0.3 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Fill

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	5	D: 0.00-0.30 m	Not Encountered	304.0	0.0			FILL - Silty SAND: fine to coarse grained, pale brown; trace gravel, fine to coarse grained, sub-angular to sub rounded, sandstone.	D		FILL
		13										
		17										
		30/10			303.0	1.0			Terminated at 0.30 m. Refusal on inferred boulder.			
					302.0	2.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland near Cataract Creek south of Picton Road

Project No: 60739890

Logged by: AL

Start Date: 09/11/25

Checked by: PW

End Date: 09/11/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 0.6 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 303014.10


Northing: 6195335.20

Hor. Datum: MGA2020-56

RL: 305 m

Ver. Datum: AHD

Surface: Fill

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	6 17 24 21 30 32	D: 0.00-0.60 m	Not Encountered	305.0	0.0			FILL - Gravelly SAND: fine to coarse grained, black mottled grey; gravel, fine to coarse grained, sub-angular to sub-rounded, coal waste.	D		FILL
						304.0 303.0 302.0			Terminated at 0.60 m.			

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush south of Picton Road between Cataract Creek and Angels Creek

Project No: 60739890

Logged by: KM

Start Date: 13/11/25

Checked by: PW

End Date: 13/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 302279.60

RL: 348 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6194953.30

Ver. Datum: AHD

Total Depth: 0.4 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.10 m	Not Encountered	348.0	0.0		SP	TOPSOIL - Clayey SAND: fine to coarse grained, dark brown; trace gravel, medium to coarse grained, sub-angular, sandstone; trace rootlets.	D		TOPSOIL
		10	D: 0.10-0.40 m			Gravelly SAND: fine to coarse grained, dark brown; gravel, fine to coarse grained, sub-angular, XW sandstone.				RESIDUAL		
		5				D	D to VD					
		11										
		9						Terminated at 0.40 m. Refusal on inferred top of rock.				
9												
8												
11												
16/50												
					347.0	1.0						
					346.0	2.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush south of Picton Road between Cataract Creek and Angels Creek

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 0.4 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Project No: 60739890

Logged by: KM

Start Date: 13/11/25

Easting: 302034.70

Northing: 6194609.70

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 13/11/25

Location Meth.: DGPS

RL: 366 m

Ver. Datum: AHD

Surface: Fill

[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush south of Picton Road between Cataract Creek and Angels Creek

Driller: AECOM**Drill Rig:** Hand Auger

Total Depth: 1.2 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Project No: 60739890

Logged by: KM

Start Date: 13/11/25

Easting: 301801.30

Northing: 6194338.40

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 13/11/25

Location Meth.: DGPS

RL: 374 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.20-1.00 m ES: 0.20-1.00 m PID=0.4 PPM	Not Encountered	374.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, pale brown.	D		TOPSOIL
		1										
		3				SP	Organic SAND: medium to coarse grained, yellow brown.			RESIDUAL		
		2										
		3										
		3										
		6										
		6										
		5										
		9										
		9				SM	Silty SAND: medium to coarse grained, yellow brown mottled grey; trace gravel, fine to coarse grained, sub-angular, XW sandstone.	M	D to VD	EXTREMELY WEATHERED SANDSTONE		
		27/30										
			PID=0 PPM					Terminated at 1.20 m. Refusal on inferred top of rock.				

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush south of Picton Road between Angels Creek and Mount Keira Road
Driller: AECOM
Drill Rig: Hand Auger
Total Depth: 0.81 m

Hole Diameter: 76 mm
Inclination: 90°
Bearing: N/A

Project No: 60739890
Logged by: AL
Start Date: 18/11/25
Easting: 301005.50
Northing: 6194011.40
Hor. Datum: MGA2020-56

Checked by: PW
End Date: 18/11/25
Location Meth.: DGPS
RL: 411 m
Ver. Datum: AHD
Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.35 m D: 0.35-0.81 m	Not Encountered	411.0	0.0			TOPSOIL - Silty SAND: fine to medium grained, grey; trace rootlets.	M		TOPSOIL
		0										
		1										
		1										
		3										
		3										
		5										
		12db										
									Terminated at 0.81 m. Refusal on inferred top of rock.			
					410.0	1.0						
					409.0	2.0						
					408.0	3.0						

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush south of Picton Road between Mount Keira Road and reverse curves

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 1.91 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Project No: 60739890

Logged by: KM

Start Date: 14/11/25

Easting: 300355.80

Northing: 6194319.80

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 14/11/25

Location Meth.: DGPS

RL: 415 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	2	D: 0.00-0.20 m ES: 0.00-0.20 m PID=0.1 PPM	▼	415.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, dark brown; trace gravel, coarse grained, sub-angular, sandstone.	M		TOPSOIL
		4	D: 0.20-0.60 m ES: 0.20-0.60 m PID=0.3 PPM				SC	Clayey SAND: fine to coarse grained, grey to dark grey.	M	MD	RESIDUAL	
		3										
		4										
		5										
		3	D: 0.60-1.20 m ES: 0.60-1.20 m PID=0.2 PPM				SP	SAND: fine to coarse grained, grey; with clay.		MD		
		3										
		3										
		6										
		8										
		8										
		12	D: 1.20-1.60 m ES: 1.20-1.60 m PID=0.2 PPM				SC	Clayey SAND: medium grained, orange grey.				
		19										
		16										
		14										
		11	D: 1.60-1.91 m ES: 1.60-1.91 m PID=0 PPM				SC	Clayey SAND: medium grained, dark yellow and grey.				
		21										
		30/85										
					413.0	2.0			Terminated at 1.91 m. Target depth.			

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush south of Picton Road between Mount Keira Road and reverse curves

Project No: 60739890

Logged by: KM

Start Date: 14/11/25

Easting: 299947.90

Northing: 6195056.20

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 14/11/25

Location Meth.: DGPS

RL: 435 m

Ver. Datum: AHD

Surface: Topsoil

Driller: AECOM


Hole Diameter: 76 mm

Drill Rig: Hand Auger

Inclination: 90°

Total Depth: 0.56 m

Bearing: N/A

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.10 m	Not Encountered	435.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, brown; trace rootlets.	D		TOPSOIL
		2	D: 0.10-0.32 m					FILL - Gravelly SAND: fine to coarse grained, dark brown; gravel, fine to coarse grained, sub-angular, sandstone.	D	FILL		
		3	D: 0.32-0.56 m				SP	Gravelly SAND: fine to coarse grained, brown grey; gravel, fine to coarse grained, sub-angular, XW sandstone.	D	MD to VD	RESIDUAL	
		15										
		11/5										
												Terminated at 0.56 m. Refusal on inferred top of rock.
					434.0	1.0						
					433.0	2.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush off Firetrail No 8b

Project No: 60739890

Logged by: AL

Start Date: 07/11/25

Checked by: PW

End Date: 07/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 298537.90

RL: 454 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6196304.60

Ver. Datum: AHD

Total Depth: 0.3 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Fill

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.30 m ES: 0.00-0.30 m PID=0 PPM	Not Encountered	454.0	0.0			FILL - SAND: fine to medium grained, yellow brown; with gravel, fine to coarse grained, sub-angular to sub-rounded, sandstone; with clay; trace rootlets.	D		FILL
		6										
		13										
		19/20			453.0	1.0			Terminated at 0.30 m. Refusal on inferred top of rock.			

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush south of Picton Road between Firetrail No 8B and Cordeaux Mine Road

Project No: 60739890

Logged by: AL

Start Date: 06/11/25

Easting: 297091.20

Northing: 6197817.00

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 06/11/25

Location Meth.: DGPS

RL: 417 m

Ver. Datum: AHD

Surface: Residual Soil

Driller: AECOM

Hole Diameter: 76 mm

Drill Rig: Hand Auger

Inclination: 90°

Total Depth: 0.15 m

Bearing: N/A

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	9db	D: 0.00-0.15 m	Not Encountered	417.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, brown; trace gravel, fine to coarse grained, sub-rounded, sandstone.	D		TOPSOIL
					416.0	1.0			Terminated at 0.15 m. Refusal on inferred top of rock.			
					415.0	2.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush south of Picton Road between Firetrail No 8B and Cordeaux Mine Road

Driller: AECOM**Drill Rig:** Hand Auger

Total Depth: 0.6 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Project No: 60739890

Logged by: AL

Start Date: 06/11/25

Easting: 295668.90

Northing: 6198691.70

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 06/11/25

Location Meth.: DGPS

RL: 389 m

Ver. Datum: AHD

Surface: Residual Soil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	9	D: 0.00-0.30 m ES: 0.00-0.30 m PID=0.3 PPM D: 0.30-0.60 m ES: 0.30-0.60 m PID=0.3 PPM	Not Encountered	-389.0	0.0			TOPSOIL - Clayey SAND: fine to coarse grained, brown; trace gravel, fine to coarse grained, sub-angular, sandstone.	D		TOPSOIL
		16										
		21						SP	Gravelly SAND: fine to medium grained, yellow brown, mottled red; gravel, fine to coarse grained, sub-angular, XW sandstone.	D	VD	EXTREMELY WEATHERED SANDSTONE
		16										
		22										
		18										
		15						Terminated at 0.60 m. Refusal on inferred top of rock.				
		22										
		40/50										
					-388.0	1.0						
					-387.0	2.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush north of Picton Road between Firetrail No 8B and Cordeaux Mine Road

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 0.45 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Project No: 60739890

Logged by: KM

Start Date: 14/11/25

Easting: 293543.60

Northing: 6200101.70

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 14/11/25

Location Meth.: DGPS

RL: 382 m

Ver. Datum: AHD

Surface: Topsoil

[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush south of Picton Road between Cordeaux Dam Road and Cordeaux Dam Road

Project No: 60739890

Logged by: AL

Start Date: 07/11/25

Easting: 291765.40

Northing: 6201917.70

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 07/11/25

Location Meth.: DGPS

RL: 341 m

Ver. Datum: AHD

Surface: Topsoil

Driller: AECOM

Hole Diameter: 76 mm

Drill Rig: Hand Auger

Inclination: 90°

Total Depth: 0.5 m

Bearing: N/A

[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush south of Picton Road between Cordeaux Dam Road and Cordeaux Dam Road

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 0.53 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Project No: 60739890

Logged by: AL

Start Date: 18/11/25

Easting: 291749.40

Northing: 6201937.90

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 18/11/25

Location Meth.: DGPS

RL: 340 m

Ver. Datum: AHD

Surface: Topsoil

[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush south of Picton Road between Cordeaux Dam Road and Cordeaux Mine Road

Driller: AECOM**Drill Rig:** Hand Auger

Total Depth: 1.7 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Project No: 60739890

Logged by: AL

Start Date: 07/11/25

Easting: 291555.60

Northing: 6202467.10

Hor. Datum: MGA2020-56

Checked by: PW

End Date: 07/11/25

Location Meth.: DGPS

RL: 323 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)	
HA	U	3	D: 0.00-0.50 m	Not Encountered	323.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, brown; with gravel, fine to coarse grained, sub-angular, sandstone; trace rootlets.	D		TOPSOIL	
		4											
		5											
		4											
		3											
		5	D: 0.50-1.00 m					FILL - Clayey SAND: fine to coarse grained, dark brown; trace gravel, fine grained, sub-rounded, sandstone.	M		FILL		
		3											
		3											
		3											
		6											
		7	D: 1.00-1.20 m				CL	Sandy CLAY: low plasticity, yellow-brown; sand, fine to medium grained.			RESIDUAL		
		6											
		5			D: 1.20-1.50 m			From 1.2 m, becoming orange-brown, medium plasticity.				w ≈ LL	VSt
		4											
		5											
		10			CH	Sandy CLAY: high plasticity, pale grey mottled red; sand, fine to coarse grained .	w < PL	H					
		21											
		20				321.0	2.0			Terminated at 1.70 m. Target depth.			
		15											
30													

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush west of Picton Road east of Firetrail No 11

Project No: 60739890

Logged by: KM

Start Date: 13/11/25

Checked by: PW

End Date: 13/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Drill Rig: Hand Auger

Inclination: 90°

Total Depth: 0.6 m

Bearing: N/A

Easting: 289582.90

Northing: 6204284.70

Hor. Datum: MGA2020-56

RL: 314 m

Ver. Datum: AHD

Surface: Topsoil

[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush west of Picton Road east off Alkoomie Place

Project No: 60739890

Logged by: AL

Start Date: 18/11/25

Checked by: PW

End Date: 18/11/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 1.5 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 289418.60

Northing: 6205412.90

Hor. Datum: MGA2020-56

RL: 304 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	1	D: 0.00-0.30 m ES: 0.00-0.30 m PID=0.4 PPM	Not Encountered	304.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, brown; trace gravel, fine to coarse grained, angular, sandstone.	D		TOPSOIL
		3										
		6										
		8	D: 0.30-1.22 m ES: 0.30-1.22 m PID=0 PPM				CI-CH	Sandy CLAY: medium to high plasticity, orange brown mottled red; sand, fine to coarse grained; trace gravel, fine to coarse grained, angular, XW sandstone.			RESIDUAL	
		10										
		12										
		9										
		7										
		13										
		8										
		8										
		11	D: 1.22-1.50 m ES: 0.30-1.22 m PID=0 PPM									
		9										
		7										
		8										
		8							Terminated at 1.50 m. Target depth.			
		11										
		9										
		7										
		15										
		30/20										

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush west of Picton Road east off Alkoomie Place

Project No: 60739890

Logged by: KM

Start Date: 17/11/25

Checked by: PW

End Date: 17/11/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 0.96 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 289463.70

Northing: 6205740.60

Hor. Datum: MGA2020-56

RL: 299 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	5	D: 0.00-0.45 m	Not Encountered	299.0	0.0			TOPSOIL - Silty CLAY: low plasticity, brown; trace gravel, fine to medium grained, sub-angular, sandstone; trace sand, fine to coarse grained.	D		TOPSOIL
		5										
		12										
		16										
		21	D: 0.45-0.80 m					CH	Silty CLAY: high plasticity, brown; with sand, fine to medium grained; trace gravel, fine to coarse grained, sub-angular, sandstone and claystone.		w < PL	H
		13										
		11										
		13										
		15	D: 0.80-0.96 m					CI-CH	Sandy CLAY: medium to high plasticity, pale brown mottled grey; sand, fine to coarse grained; trace gravel, fine to coarse grained, sub-angular, sandstone.		w < PL	H
		14										
		30			298.0	1.0			Terminated at 0.96 m. Refusal on inferred top of rock.			
		30/40										
					297.0	2.0						
					296.0	3.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush west of Picton Road east off Macarthur Drive

Project No: 60739890

Logged by: AL

Start Date: 17/11/25

Checked by: PW

End Date: 17/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Drill Rig: Hand Auger

Inclination: 90°

Total Depth: 0.72 m

Bearing: N/A

Easting: 289573.70

Northing: 6205690.60

Hor. Datum: MGA2020-56

RL: 302 m

Ver. Datum: AHD

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)	
HA	U	3	D: 0.00-0.50 m	Not Encountered	302.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, brown; trace gravel, fine to coarse grained, sub-angular, sandstone; trace rootlets.	D		TOPSOIL	
		5											
		5											
		4											
		11					D: 0.50-0.72 m D: 0.50-0.72 m		SM	Silty SAND: fine to coarse grained, brown; trace gravel, fine to coarse grained, sub-angular, XW sandstone; trace coal.	D	H	EXTREMELY WEATHERED SANDSTONE
		29/90											
									Terminated at 0.72 m. Refusal on inferred top of rock.				

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Bush west of Picton Road east off Alkoomie Place

Project No: 60739890

Logged by: KM

Start Date: 17/11/25

Checked by: PW

End Date: 17/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 289519.30

RL: 291 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6205994.50

Ver. Datum: AHD

Total Depth: 0.8 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	6	D: 0.00-0.45 m	Not Encountered	-291.0	0.0			TOPSOIL - Silty CLAY: low plasticity, brown; trace rootlets.	w < PL		TOPSOIL
		11										
		12										
		12										
		14	D: 0.45-0.80 m				CI	Sandy CLAY: medium plasticity, brown; trace sand, medium to coarse grained.	w < PL	H	RESIDUAL	
		12										
		14										
		17										
		29							Terminated at 0.80 m. Hand auger refusal.			
		22										
		20										
		18										
		21										
		29										
		31/50										

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland east of Almond Street

Project No: 60739890

Logged by: AL

Start Date: 05/12/25

Checked by: PW

End Date: 05/12/25

Location Meth.: DGPS

Driller: AECOM

Drill Rig: Hand Auger

Total Depth: 0.84 m

Hole Diameter: 76 mm

Inclination: 90°

Bearing: N/A

Easting: 287929.90



Northing: 6208421.50

Hor. Datum:

RL: 225 m

Ver. Datum: AHD

Surface: Fill

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	2	D: 0.00-0.45 m ES: 0.00-0.45 m PID=0.2 PPM	Not Encountered	225.0	0.0			FILL - Sandy CLAY: low plasticity, brown; sand, medium to coarse grained ; trace gravel, fine to medium grained, sub-angular, sandstone.	w < PL		FILL
		3										
		3										
		4										
		2	D: 0.45-0.80 m ES: 0.45-0.80 m PID=0.1 PPM						FILL - Sandy CLAY: medium plasticity, dark brown; sand, medium to coarse grained ; trace gravel, fine to medium grained, sub-angular, sandstone .	w < PL		
		5										
		17										
		17										
		20	D: 0.80-0.84 m ES: 0.80-0.84 m PID=0 PPM				CI-CH	Gravelly Sandy CLAY: medium to high plasticity, yellow-brown; gravel, fine to medium grained, sub-angular, sandstone ; sand, fine to coarse grained. Terminated at 0.84 m. Refusal on inferred top of rock.	w < PL	H	RESIDUAL	

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland south of Cordeaux Dam Main Access Gate

Project No: 60739890

Logged by: AL

Start Date: 18/11/25

Checked by: PW

End Date: 18/11/15

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 295369.90

RL: 376 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6199124.20

Ver. Datum: AHD

Total Depth: 0.82 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)			
HA	U	5	D: 0.00-0.55 m D: 0.55-0.82 m	Not Encountered	376.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, brown; trace gravel, fine to coarse grained, sub-angular to sub-rounded, sandstone.	D		TOPSOIL			
		11													
		8													
		5													
		8						SP	SAND: fine to coarse grained, brown, mottled orange; trace gravel, fine to coarse grained, angular, XW sandstone. From 0.75 m, becoming orange brown mottled red.				M	D to VD	RESIDUAL
		12													
		11													
		8													
								Terminated at 0.82 m. Refusal on inferred top of rock.							
		10			375.0	1.0									
	3														
30/20															

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Grassland south of Cordeaux Mine Main Access Gate

Project No: 60739890

Logged by: AL

Start Date: 19/11/25

Checked by: PW

End Date: 19/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 292666.10

RL: 349 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6200738.30

Ver. Datum: AHD

Total Depth: 0.85 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / REMARKS DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
HA	U	6	D: 0.00-0.30 m	Not Encountered	-349.0	0.0			TOPSOIL - Silty SAND: fine to coarse grained, pale brown; trace gravel, fine grained, sub-angular, sandstone.	D		TOPSOIL
		10										
		8										
		6	D: 0.30-0.66 m				SM	Silty SAND: fine to coarse grained, yellow brown; trace gravel, fine to medium grained, sub-angular, sandstone.	D	MD to D	RESIDUAL	
		5										
		4										
		3	D: 0.66-0.85 m				SM	Silty SAND: fine to coarse grained, orange brown mottled red; with gravel, fine to medium grained, sub-angular to angular, XW sandstone.	D	D to VD		
		14										
		6										
		30/90			-348.0	1.0		Terminated at 0.85 m. Hand auger refusal.				
					-347.0	2.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Bush off Firetrail No 8c

Project No: 60739890

Logged by: AL

Start Date: 19/11/25

Checked by: PW

End Date: 19/11/25

Location Meth.: DGPS

Driller: AECOM

Hole Diameter: 76 mm

Easting: 292666.20

RL: 310 m

Drill Rig: Hand Auger

Inclination: 90°

Northing: 6200745.50

Ver. Datum: AHD

Total Depth: 1.61 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Topsoil

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)		
HA	U	1	D: 0.20-1.00 m	Not Encountered	310.0	0.0			TOPSOIL - Silty CLAY: low plasticity, brown; trace rootlets.	w < PL		TOPSOIL		
		3												
		4							CL	Silty CLAY: low plasticity, brown; trace gravel, fine grained, sub-rounded, sandstone and claystone.		VSt	RESIDUAL	
		6												
		5												
		7												
		9												
		11												
		11												
		12												
		12	D: 1.00-1.61 m						CL	Sandy CLAY: low plasticity, red brown; sand, fine to coarse grained; trace gravel, fine to coarse grained, sub-angular to angular, sandstone and claystone.				H
		14												
		13												
		18												
		18												
		20												

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.