

Client: TfNSW

Project: Picton Road Upgrade

Location: Field South of Alkoomie Place

Project No: 60739890

Logged by: VT

Start Date: 10/12/25

Checked by: PW

End Date: 10/12/25

Location Meth.: DGPS

Operator: Durkin

Dimensions: 2 m x 0.6 m

Easting: 289397.20

RL: 303.1 m

Plant: 5t Excavator (450 mm)

Orientation: Longitudinal

Northing: 6205356.00

Ver Datum: AHD

Total Depth: 1.7 m

Surface: Topsoil

Hor. Datum: MGA2020-56

METHOD	SUPPORT	GROUND WATER	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
E	U	Not Encountered	6	B: 0.00-0.15 m	303.0	0.0			TOPSOIL - Silty CLAY: low plasticity, pale brown; with sand, fine to coarse grained; trace rootlets, trace charcoal.	w < PL		TOPSOIL
			9	B: 0.15-1.10 m				CI-CH	CLAY: medium to high plasticity, pale brown to red brown; trace sand, medium to coarse grained; trace gravel, fine to medium grained, rounded to sub-rounded, shale, sandstone; trace rootlets.		VSt	RESIDUAL
			6									
			9									
			12									
			12									
			12									
			10								H	
			10									
			9									
			8			1.0						
			22	B: 1.10-1.30 m	302.0			CL	Gravelly CLAY: low plasticity, grey; gravel, medium to coarse grained, angular to sub-angular, shale; extremely weathered material.	D	H	EXTREMELY WEATHERED SHALE
			18									BEDROCK
			19	B: 1.30-1.70 m					SHALE: dark grey, HW, VL strength.			
			20									
									Terminated at 1.70 m. Target depth.			

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

TEST PIT PHOTO REPORT

TEST PIT NO. : PRUP_TP01

PROJECT : Picton Road Upgrade
LOCATION : Field South of Alkoomie Place

PROJECT NO. : 60739890
Sheet 1 of 2



AECOM

TEST PIT PHOTO REPORT

TEST PIT NO. : PRUP_TP01

PROJECT : Picton Road Upgrade

PROJECT NO. : 60739890

LOCATION : Field South of Alkoomie Place

Sheet 2 of 2



AECOM

Client: TfNSW
Project: Picton Road Upgrade
Location: Alkoomie Place

Project No: 60739890
Logged by: VT
Start Date: 10/12/25

Checked by: PW
End Date: 10/12/25
Location Meth.: DGPS
Ver Datum: AHD

Operator: Durkin
Plant: 5t Excavator (450 mm)
Total Depth: 1.4 m

Dimensions: 2 m x 0.6 m
Orientation: Longitudinal
Surface: Topsoil

Easting: 289338.50
Northing: 6205928.00
Hor. Datum: MGA2020-56

METHOD	SUPPORT	GROUND WATER	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
E	U	Not Encountered	10	B: 0.00-0.10 m ES: 0.00-0.10 m PID=0.6 PPM	289.0	0.0			TOPSOIL - Silty CLAY: low plasticity, brown; with sand, fine to coarse grained; trace rootlets.	w < PL		TOPSOIL
			19			CL	Sandy CLAY: low plasticity, pale brown; sand, fine to coarse grained; trace gravel, fine to coarse grained, sub-rounded to rounded, ironstone; trace rootlets.	w < PL	H	RESIDUAL		
			20									
			14									
			13									
			15									
			14									
			10	B: 0.80-1.35 m ES: 0.80-1.35 m PID=0.4 PPM			CI-CH	CLAY: medium to high plasticity, pale grey mottled red; trace sand, fine to coarse grained; trace gravel, fine to medium grained, sub-angular to sub-rounded, sandstone.	w < PL	VSt to H		
			11									
			6									
			10									
			8									
			6									
			20									
								SANDSTONE: fine to medium grained, pale grey.			EXTREMELY WEATHERED SANDSTONE	
				Terminated at 1.40 m. Refusal on inferred top of rock.								
					288.0							
					2.0							
					287.0							

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

TEST PIT PHOTO REPORT

TEST PIT NO. : PRUP_TP02

PROJECT : Picton Road Upgrade
LOCATION : Alkoomie Place

PROJECT NO. : 60739890
Sheet 1 of 2



AECOM

TEST PIT PHOTO REPORT

TEST PIT NO. : PRUP_TP02

PROJECT : Picton Road Upgrade
LOCATION : Alkoomie Place

PROJECT NO. : 60739890
Sheet 2 of 2



AECOM