SUBJECT: CLARIFICATION ON VEHICLE INSPECTION AUDIT FINDINGS FOR A MOTOR VEHICLE REGISTRATION NUMBER KCL 971X INSPECTED ON 9TH JUNE 2025

I am writing to address the query raised regarding the inspection of a motor vehicle registration number KCL 971X that was inspected on 9th June 2025. On that day, accompanied by the ISO auditor and an attachee we inspected the vehicle in question and identified the following defects as per the photo below.

1. Faded chevrons (Rear)
2. Faded reflectors (front and rear)

I proceeded and instructed the clerk to fail the vehicle in the system as per the defects which was done as shown below.

Comments

Inspector Name

GEORGE WARUINGI KIARIE

List of Owners

EDWARD KAAHE KANYI
, MARY WAMBURA WAHETI

Vehicle Details

Registration Number

KCL971X

Chassis Number

ADMARRJR8G4803494

Engine Number

4JK1PZ3047

Body Type

VAN/PICKUP

Make

ISUZU

Vehicle Use

COMMERCIAL

Tare Weight

1850

Load Capacity

1000

1/1



SECTION 6 – TEST DRIVE

SPEEDOMETER

Pass
Fail

SPEED GOVERNOR CONDITION (TYPE AND OPERATION)

Pass
Fail

VEHICLE CONTROL AND STABILITY ON TEST DRIVE

Pass
Fail

SERVICE BREAK EFFICIENCY AND BALANCE

Pass
Fail

PARKING BREAK CONDITION (TESTED ON RAMP)

Pass
Fail

SMOKE EMMISSION

Pass
Fail

TRAILER COUPLING/OTHER CONNECTIONS

Pass
Fail

Remarks

Overall Results

Pass
Fail

Overall Comment

REPLACE CHEVRONS AND REFLECTORS

Inspecting Officer

GEORGE WARUINGI KIARIE

As per standard procedure, the vehicle owner was instructed to rectify these defects and return for re- inspection.

Upon the vehicle's return after rectifying the identified defects, I conducted a physical re-inspection and confirmed that it met the required standards. Based on this verification, I proceeded to issue the inspection sticker without verifying the initial failure and subsequent re-inspection outcome. This decision was based on my professional judgment that the vehicle had adequately addressed the previously noted defects as shown in the images bellow.

ISUZU
KCL 971X

Regarding the query on why we issue inspection stickers without vehicle passing through the inspection pit, we wish to clarify that our inspection centre does not have a designated inspection pit. Instead, vehicle inspections are conducted in an open field area designated for this purpose, where our team carries out thorough examinations in accordance with standard operating procedures as shown in the image bellow.



Due process was followed in inspecting, failing and re-inspection of the said vehicle hence it was issued with a sticker.